

Erosion Severity

SUMMIT CANYON

 No Erosional Problems Observed Summit Canyon Property not surveyed for erosion.
 Property acquired after surveys completed.

Reference Features

Donner Memorial State Park

---- Streams

---- Non-system Route

—— Highways

—— Local Road

----- Other Agency Trail

Parking

Map Page Location



Scale 1:6,000 1 inch = 500 fee

1 inch = 500 feet

Feet

250 500

Donner Memorial State Park Road and Trail Management Plan

NOTES

Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

CALIFORNIA STATE PARKS SIERRA DISTRICT & PLANNING DIVISION Date: 10/6/2020

Sources: Calif. Dept. of Parks & Recreation Other Public Lands GreenInfo, Inc.

