

Plan Recommendations

DM #1. Diablo Mines Area Trail Rereroutes and and removals. Issue: Redundant routes which have the potential to impact sensitive habitat. Two distinct areas defined. Rec: Remove and / or reroute trails as necessary to protect habitat and provide loop and destination trail experiences.

DM #2. Ridgeline and Power Line Service Rd Issue: Improved trail connectivity and loop trail opportunities. Recommendation: Establish trail connection between Ridgeline Trl and Power Line Service Rd.

DM #3. Quicksilver Trl. Issue: Trail extends onto private property and into sensitive habitat.. Rec: Reroute trail away from private property. Inventory and give protection measures for rare plants.

DM #4. Blaisdell Trl. Issue: Very steep, little used, unsustainable, redundant. Rec: Remove and rehabilitate Blaisdale Trl segments 2,3. Use Sattler Trl as alternate.

DM #5. Perkins Canyon Issue: Limited visitor access to Diablo Mines area. Rec: Develop a 20-25 car parking lot, staging area, and install restoom and drinking fountain.

DM #6. Power Tower Area to Prospector's Gap Rd-3 Connection Issue: Isolated portion of the park with no trail connections to other park facilities and experiences. Rec: Work with Save Mount Diablo to investigate possible trail route from the Power Tower portion of the Diablo Mines area to Prospector's Gap Road-3 using Calif State Park's and Save Mount Diablo's properties.

