



Potential Significance to Water Resources & Drainage Structure Condition Index

MITCHELL CANYON TO SUMMIT

Potential Road and Trail Impacts To Water Resources

- High
- Medium
- Low

Drainage Structure Condition Index
Higher Score = poor condition of structure

- Low
- Medium
- High

— Park Roads / Trails with No Significant Impact to Water Resources
 — Local Roads
 — Paved Park Roads

Museum/Visitor center
 Campground
 Mt Diablo State Park
 Other Public Lands
 Public Access Limits
 No Access
 Intermittent Stream

Map Page Location

Scale
1:22,772
1 inch = 1,898 feet

Mount Diablo State Park Road and Trail Management Plan

NOTES:
Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

<p>FACILITIES MANAGEMENT DIVISION</p>	<p>Date: 1/27/2015 Sources: Calif. Dept. of Parks & Recreation Calif. Geologic Survey Road and Trail Inventory Other Public Lands: GreenInfo, Inc.</p>	
--	--	--