



Potential Significance to Water Resources & Drainage Structure Condition Index

NOTHGATE TO SUMMIT

Potential Road and Trail Impacts To Water Resources

- High (Red line)
- Medium (Yellow line)
- Low (Green line)

Drainage Structure Condition Index
Higher Score = poor condition of structure

- Low (Small circle)
- Medium (Medium circle)
- High (Large circle)

— Park Roads / Trails with No Significant Impacts to Water Resources
— Local Roads
— Paved Park Roads

Other Public Lands

Public Access Limits

- No Access (Cross-hatched box)
- Restricted Access (Diagonal lines box)
- Intermittent Stream (Dotted blue line)

Map Page Location

Scale
1:27,257
1 inch = 2,271 feet

Miles
0 0.1 0.2 0.3 0.4 0.5

Mount Diablo State Park Road and Trail Management Plan

NOTES:
Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

<p>FACILITIES MANAGEMENT DIVISION</p>	<p>Date: 1/28/2015 Sources: Calif. Dept. of Parks & Recreation Calif. Geologic Survey Road and Trail Inventory Other Public Lands: GreenInfo, Inc.</p>	
--	--	--