



Potential Significance to Water Resources & Drainage Structure Condition Index

SOUTHGATE TO SUMMIT

Potential Significance To Water Resources

- High
- Medium
- Low

Drainage Structure Condition Index
Higher Score=poor condition of structure

- Low
- Medium
- High

— Park Roads / Trails with No Significant Impact to Water Resources
— Local Rds
— Paved Park Roads

Museum/Visitor center Mt Diablo State Park
 Campground Intermittent Stream
 Group Camp
 Horse Camp

Map Page Location

Scale
1:24,000
1 inch = 2,000 feet

Miles
0 0.1 0.2 0.3 0.4 0.5

Mount Diablo State Park Road and Trail Management Plan

NOTES:
Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

FACILITIES MANAGEMENT DIVISION	Date: 1/28/2015 Sources: Calif. Dept. of Parks & Recreation Calif. Geologic Survey Road and Trail Inventory Other Public Lands: GreenInfo, Inc.	
---	---	--